This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

















. •

Pattern of Metal Vias 122 Dielectric Film 126

Align pattern of metal vias 122 with the metal pattern 108 and the metal pattern

116

Heat the assembly 1200 is heated to electrically couple the metal pattern 108 to the metal pattern 116

Dispose a thermosetting plastic in liquid or fluid form in the gaps 1304 and/or 1306 and cure thermosetting plastic

